

Indoor photos (a selection of indoor photos have been added to the album, numbered with the number of the image file)

Central staircase

Photo 14.1st floor



Photo 21. 2nd floor



Photo 497. 3rd floor



Eastern staircase

Photo 510. 1st floor



Photo 508. 1st floor



Photo 18. 2nd floor



Photo 458. 3rd floor



Gorge 1st floor sector 1

Photo 523. 1st floor, staff lounge with fireplace



Photo 695. 1st floor, staff lounge front room with mirror
Photo 699. 1st floor, kitchenette of the staff lounge



Photo 338. 1st floor sector 1 staff pool in the front room of sauna in the half-tower



Photo 519. 1st floor garage



Photo 633. 1st floor louse-hell



Gorge 1st floor sector 2
Photo 522. 1st floor staff gym



Gorge 2nd floor sector 1
Photo 311. 2nd floor prisoners' washroom



Photo 306. 2nd floor corridor



Photo 288. 2nd floor corridor




Photo 284. 2nd floor cell



Photo 281. 2nd floor cell



Photo 708. Officer booth of new prisoners' distribution point



Photo 271. 2nd floor photographing room



Photo 716. Turkish-style concrete toilet holes in the half-tower



Photo 721. Compartment



Gorge 2nd floor sector 2
Photo 77. 2nd floor corridor



Photo 68. 2nd floor corridor



Photo 48. 2nd floor cell



Photo 61. 2nd floor cell



Photo 22. 2nd floor corridor



Photo 713. 2nd floor trellis with mirror in the corridor

Photo 22. 2nd floor corridor



Gorge 3rd floor sector 1

Photo 425. 3rd floor casemate of the end of the east wing, passage to the 4th floor of the individual chamber building



Photo 429. 3rd floor casemate of the end of the east wing



Photo 437. 3rd floor corridor



Photo 445. 3rd floor cell



Photo 450. 3rd floor corridor



Photo 451. 3rd floor auxiliary room



Photo 456. 3rd floor former church, waiting room for court decision



Photo 464. 3rd floor compartment



Photo 466. 3rd floor half-tower



Gorge 3rd floor sector 2

Photo 460. 3rd floor corridor




Photo 479. 3rd floor cell



Photo 487. 3rd floor corridor



Photo 493. 3rd floor auxiliary room



Individual Chamber building 1st floor

Photo 527. 1st floor



Photo 526. 1st floor




Photo 531. 1st floor



Photo 543. 1st floor cell



Photo 544. 1st floor cell



Individual Chamber building 2nd floor

Photo 314. 2nd floor



Photo 315. 2nd floor



Photo 334. 2nd floor



Photo 349. 2nd floor cell



Photo 347. 2nd floor cell



Individual Chamber building 3rd floor

Photo 360. 3rd floor



Photo 371. 3rd floor



Photo 366. 3rd floor cell



Individual Chamber building 4th floor

Photo 389. 4th floor



Photo 390. 4th floor



Photo 391. 4th floor



Photo 394. 4th floor



Photo 402. 4th floor cell



Attic

Photo 198



Photo 205. Metal tanks in the attic



Lunette

Lunette 1st floor

Photo 214. Waiting room in the Prisoners' visitor centre



Photo 215. Meeting room in the prisoners' visitor centre



Photo 215. Vestibule of the prisoners' visitor centre, front door



Photo 223. Corridor



Photo 226. Stencil paintings



Photo 228.



Photo 238



Lunette 2nd floor

Photo 241



Photo 242




Photo 243

Photo 726



Lunette 3rd floor

730.

731.



Photo 246.

